

FORD:

2005 Five Hundred, Focus, Freestyle,
Mustang, F-150

MERCURY:

2005 Montego

ISSUE

Some 2005 Freestyle, Five Hundred/Montego vehicles built 5/17/2004 through 2/24/2005, and 2005 Mustang, Focus, F-150 vehicles, all vehicles equipped with a single or 6 disk CD player with MP3 capability, may exhibit one or more of the following intermittent CD player concerns.

- CD player skips
- Locks up when playing homemade CDs
- Displays "Error" or "Bad Disc"
- Will not accept CDs
- CD inoperative or inconsistent playability of some CDRs.

ACTION

Replace CD player with latest service level through your facing audio service center. When replacing the audio unit (radio) on 2005 Freestyle, Five Hundred, Montego and Mustang vehicles it is necessary to perform programmable module installation (PMI) prior to removal of the old audio unit. This information must be uploaded into the new audio unit once installed. Failure to perform PMI on the new audio unit may result in inoperative backlighting and/or diagnostic trouble code (DTC) B2477. If communication cannot be established with old audio unit to download this information, as built data will need to be used. As built data can be obtained at the Professional Technician Society (PTS) website or at www.motorcraft.com. For additional information, refer Workshop Manual Section 415-01 and 418-01.

PART NUMBER	PART NAME
-18806-	Audio Unit

WARRANTY STATUS: Eligible Under Provisions Of
New Vehicle Limited
Warranty Coverage

OPERATION	DESCRIPTION	TIME
050609A	2005 Five Hundred/Freestyle/Montego: Replace CD Player (Do Not Use With 18805B Or 18805C)	0.7 Hr.
050609A	2005 Mustang: Replace CD Player (Do Not Use With 18805B Or 18805C)	0.9 Hr.
050609A	2005 Focus: Replace CD Player (Do Not Use With 18805B Or 18805C)	0.4 Hr.
050609A	2005 F-150: Replace CD Player (Do Not Use With 18805B Or 18805C)	0.3 Hr.

DEALER CODING

BASIC PART NO.	CONDITION CODE
18C815	42

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.