

RATTLE/NOISE FROM THE CENTER STACK (RADIO/HEATER) OF THE INSTRUMENT PANEL OR GEARSHIFT AREA

TSB 06-4-1

FORD:
2005-2006 Mustang

ISSUE

Some 2005-2006 Mustang vehicles may exhibit a concern with rattle/noise from either the center stack (radio/heater) of the instrument panel or gearshift area.

ACTION

The rattle/noise may be caused by one or both of the exhaust hanger isolators on the trans cross member (number 3 cross member) being loose. To determine if an isolator is loose refer to the Service Procedure.

SERVICE PROCEDURE

NOTE

VEHICLES EQUIPPED WITH A V6 ENGINE MAY HAVE THE RATTLE AT APPROXIMATELY 850 AND 1,500 RPM'S, AND THE V8 AT APPROXIMATELY 1,200 & 3,200 RPM.

1. Lightly tap the exhaust hanger isolator located on the transmission crossmember (number 3) with a dead-blow hammer. It should have a solid sound to it.
2. If the hanger has a solid sound to it, do not continue with this TSB and continue with normal diagnostics.
3. If it rattles, secure it with a screw type worm clamp. Use a 3 inch, size 40 stainless worm clamp (obtain locally). Positioned 90 degrees to the exhaust hanger rod. (Figures 1-4). The clamp can be installed without removing the crossmember.

NOTE

REFER TO TSB 05-08-06 FOR 2005 4.0L AUTOMATIC EQUIPPED CARS EXHIBITING VIBRATION/DRONE CONCERNS.

NOTE

3 INCH, SIZE 40 STAINLESS WORM CLAMPS OR EQUIVALENT SHOULD BE INSTALLED WITH THE SCREW HEAD LOCATED AT EITHER THE 3 OR 9 O'CLOCK POSITION TO MAXIMIZE GROUND CLEARANCE.

OTHER APPLICABLE ARTICLES: 05-08-06
WARRANTY STATUS: Eligible Under Provisions Of New Vehicle Limited Warranty Coverage

OPERATION	DESCRIPTION	TIME
060401A	2005-2006 Mustang: Secure One Exhaust Hanger (Do Not Use With 5200A, 1007D, 5212A, 5229A)	0.2 Hr.
060401B	2005-2006 Mustang: Secure Both Exhaust Hangers (Do Not Use With 5200A, 1007D, 5212A, 5229A)	0.3 Hr.

DEALER CODING

BASIC PART NO.	CONDITION CODE
6A023	33




Figure 1 - Article 06-4-1

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supercede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.

TSB 06-4-1 (Continued)




Figure 2 - Article 06-4-1




Figure 3 - Article 06-4-1




Figure 4 - Article 06-4-1