

Year: [2010](#)
Model: [Mustang](#)
Model: [09-26-7](#)

TSB
09-26-7

- 5.4L / 4.0L - DTC P0607

Publication Date: December 21, 2009

FORD: 2008-2010 Mustang, F-250, F-350

ISSUE:

Some 2008-2010 F-Super Duty 250-350 [vehicles](#) equipped with 5.4L engine and automatic transmissions and Mustang vehicles equipped with 4.0L engine and automatic or manual transmissions may exhibit diagnostic trouble code P0607 (control module performance) stored in the [powertrain](#) control module (PCM) memory.

ACTION:

Reprogram the PCM to the latest calibration using IDS release 64.08 and higher. This new calibration is not included in the VCM 2009.11 DVD. Calibration files may also be obtained at www.motorcraft.com.

WARRANTY STATUS:

Eligible Under Provisions Of New [Vehicle](#) Limited Warranty Coverage And Emissions Warranty Coverage
IMPORTANT: Warranty coverage limits/policies are not altered by a TSB. Warranty coverage limits are determined by the identified causal part.

OPERATION	DESCRIPTION	TIME
092607A	2008-2010 F-Super Duty 5.4L 3V, 2008-2010 Mustang 4.0L SOHC Check For DTCs And Reprogram The PCM (Do Not Use With Any Other Labor Operations)	0.3 Hr.

DEALER CODING

BASIC PART NO.	CONDITION CODE
RECALEM	04