

SATELLITE DIGITAL AUDIO RECEIVER SYSTEM (SDARS), MAY NOT SEEK ALL SIRIUS SATELLITE RADIO CHANNELS

TSB 08-5-1

FORD:

2008 Focus, Fusion, Mustang, Taurus X, Taurus, Edge, Escape Hybrid, Escape, Expedition, Explorer Sport Trac, Explorer, F-150, F-150, F-Super Duty

LINCOLN:

2008 MKZ, Mark LT, MKX, Navigator

MERCURY:

2008 Milan, Sable, Mariner Hybrid, Mariner, Mountaineer

ISSUE

Some 2008 Ford, Lincoln and Mercury vehicles equipped with Satellite Digital Audio Receiver System (SDARS) may not seek or be able to toggle through all channels in Sirius Satellite Radio mode.

ACTION

To correct this situation, set the Satellite Categories to ALL using the following instructions for the system installed in the vehicle.

SERVICE PROCEDURE

Navigation Radios

1. Press the SR button on the Radio Screen until SAT1 appears.
2. Once SAT1 appears press the Genre button so that the Category list appears. Select the Category All button.
3. Press the SR button on the Radio Screen until SAT2 appears.
4. Once SAT2 appears press the Genre button so that the Category list appears. Select the Category All button.
5. Press the SR button on the Radio Screen until SAT3 appears.
6. Once SAT3 appears press the Genre button so that the Category list appears. Select the Category All button.

You have now reset the category setting for each satellite radio mode.

Non-Navigation Radios With Built In Display

1. Press and cycle the Aux button on the Radio until SAT1 appears.
2. Once SAT1 appears press and cycle the Menu button until Category appears, Press OK.
3. The next prompt will be Category All, Press OK.
4. Press and cycle the Aux button until SAT2 appears, once SAT2 appears press and cycle the Menu button until Category appears. Press OK.
5. The next prompt will be Category All, Press OK.
6. Press and cycle the Aux button until SAT3 appears, once SAT3 appears press and cycle the Menu button until Category appears Press OK.
7. The next prompt will be Category All, Press OK.

You have now reset the category setting for each satellite radio mode.

Non-Nav Radios With External/Remote Display

1. Press the Sirius button on the Radio until SAT1 appears.
2. Once SAT1 appears press the CAT/Fold button so that the CAT icon goes away.
3. Press the Sirius button on the Radio until SAT2 appears.

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.

TSB 08-5-1 (Continued)

4. Once SAT2 appears press the CAT/Fold button so that the CAT icon goes away.
5. Press the Sirius button on the Radio until SAT3 appears.
6. Once SAT3 appears press the CAT/Fold button so that the CAT icon goes away.

You have now reset the category setting for each satellite radio mode.

WARRANTY STATUS: Eligible Under Provisions Of
New Vehicle Limited
Warranty Coverage
IMPORTANT: Warranty
coverage limits/policies are
not altered by a TSB.
Warranty coverage limits
are determined by the
identified causal part.

OPERATION	DESCRIPTION	TIME
MT080501	Claim Labor As Actual Time	Actual Time
DEALER CODING		CONDITION
BASIC PART NO.		CODE
18C851		42