

Opened: 07/24/2008 17:42  
Ready: 07/28/2008 17:26  
Miles In: 476  
Miles Out: 486

A CHECK ENGINE LIGHT IS ON

CAUSE: 486 6B288 CHECKED FOR MIL LIGHT ON. KOEO PASS KOEC P0345,P0349,  
KOER PASS. RAN OASIS NO KNOWN CONCERNS FOR THESE CODES.

CONTACTED HOTLINE,  
10 DRIVEABILITY

738 WF

1 1W7Z\*6B288\*AB SENSOR ASY

FC: PART#: COUNT:

CLAIM TYPE:

AUTH CODE:

6299

PARTS: 0.00 LABOR: 0.00 OTHER:

,,,,,486 6B288 CHECKED FOR MIL LIGHT ON. KOEO PASS KOEC P0345,P0349,  
,,,,,KOER PASS. RAN OASIS NO KNOWN CONCERNS FOR THESE CODES. CONTACTED  
,,,,,HOTLINE, DISSCUSSED POSSIBLE CAUSES. CHECKED ALTERNATOR RFI NOISE,  
,,,,,CHECKED REMOTE START FOR RFI NOISE, CHECKED COILS FOR NOISE. NO RFI  
,,,,,NOISE FOUND. CHECKED WIRING TO BANK 2 CMP SENSOR ALL PINS TIGHT AND  
,,,,,WIRING CHECKS GOOD FROM PCM CONNECTOR 175E PIN 43 TO CMP SENSOR  
,,,,,CONNECTOR C1367 PIN 2. FOUND THAT CODES WOULD RESET ON RESTART WITH IN  
,,,,,THE FIRST MINUTE OF RUNTIME. SWAPPED CMP SENSOR 1 WITH SENSOR 2. CODE  
,,,,,MOVED TQ BANK ONE (P0340). REPLACED INTERMITTANT FAILING CMP SENSOR.  
,,,,,CLEARED CODES ROADTEST RETEST, P1000.