

Opened: 07/08/2009 09:39
Ready: 07/20/2009 15:17
Miles In: 5447
Miles Out: 5561

A CUSTOMER STATES THAT LEFT QUARTER LOUVER IS LOOSE
CAUSE: 5561 CHECKED LEFT SIDE CALIFORNIA SPECIAL QUARTER PANEL SCOOP
FOR BEING LOOSE AT TOP REAR. REMOVED SCOOP, CLEANED ALL TAPE
FROM SCOOP AND

MT63279D36 REMOVE AND RETAPE MOULDING.REMOVE AND
REPLACE MOULDING.

1426 WB

(N/C)

P101 BASIC PAINT OPERATION - ONE COLOR - L

1402 WB

(N/C)

MT63279D36 REFINISH REAR QUARTER PANEL MOULDING.

1402 WB

(N/C)

1 7R3Z*63279D36*BAPTM PANEL

(N/C)

FC: PART#: COUNT:

CLAIM TYPE:

AUTH CODE:

2409

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 0.00

, , , , 5561 CHECKED LEFT SIDE CALIFORNIA SPECIAL QUARTER PANEL SCOOP FOR
, , , , BEING LOOSE AT TOP REAR. REMOVED SCOOP, CLEANED ALL TAPE FROM SCOOP AND
, , , , BODY. RETAPED SCOOP AND REINSTALLED. SCOOP STILL STICKS OUT AT TOP
, , , , REAR. ORDERED NEW SCOOP AND PAINTED TO MATCH CAR. REMOVED OLD PART AND
, , , , CLEANED BODY. INSTALLED NEW QUARTER PANEL SCOOP.