
Taco Bill 11/25/2008

This install was performed on Leo's 2006 GT. I believe the manual calls for this filter to be replaced at 30k miles. Cost of this filter can range from \$10-20 depending where you purchase it from.

Install time for this filter replacement will be around 5 minutes.







Turn key to 'ON' position and cycle windshield wipers to the up position and turn key off.



If you have aftermarket hood struts, you may need to disconnect the lower strut mount.





Using a standard Phillips screwdriver, carefully unscrew the plastic screw pin. Once unscrewed, pull up on the retaining pin. 2 places.

























After transferring the black frame from the old filter to the new filter, re-install in reverse order.







Make sure the cover is positioned back into the original location. The cover seal should sit flush up against the windshield.



Re-install screw push pins and (if removed) hood strut.





Installation complete. Enjoy your new fresh cabin air!